


TEMPERATURE CONVERSION CHART (°F and °C)

SHOWING MELTING POINTS OF COMMONLY USED ELEMENTS

Temperature Conversion:

$$\text{Degrees F} = (\text{°C} \times 9/5) + 32$$

$$\text{Degrees C} = (\text{°F} - 32) \times 5/9$$



Useful Range of Thermocouples– 458°F to + 4800°F